



06-08

Communication	Navigation	Services										
CTAF 122.9 APP/DEP 133.3	<table border="1"> <tr> <td colspan="2" data-bbox="651 1388 953 1428">Elevation. 938'</td> </tr> <tr> <td colspan="2" data-bbox="651 1428 953 1467">TPA. 1938'</td> </tr> <tr> <td colspan="2" data-bbox="651 1493 953 1528">VOR to Field:</td> </tr> <tr> <td data-bbox="651 1528 808 1564">117.0 DLL</td> <td data-bbox="808 1528 953 1564">282°/25 NM</td> </tr> <tr> <td data-bbox="651 1564 808 1600">NDB</td> <td data-bbox="808 1564 953 1600">251 HBW</td> </tr> </table>	Elevation. 938'		TPA. 1938'		VOR to Field:		117.0 DLL	282°/25 NM	NDB	251 HBW	FUEL: NONE - Airport Manager 608-489-3132
Elevation. 938'												
TPA. 1938'												
VOR to Field:												
117.0 DLL	282°/25 NM											
NDB	251 HBW											
NOTES: 1, UNATTENDED. 2. RWY 05 THRESHOLD LIGHTS BLACK (OBSCURED) AND GREEN.												