


Zoo Interchange Corridor Study
ID 1060-33-01
Milwaukee County
Examples of
Highway Roadway Deficiencies



BLUEMOUND ROAD

WISCONSIN AVENUE

POOR STOPPING
SIGHT DISTANCE

LOOKING SOUTH
OVER USH 45

Legend:

- Short Weave / Merge 
- Tight Ramp Curve 
- Narrow Shoulder 

